

	SBT Landscapes	Leisure Equipment Repairs
<b><u>Hopwas Playing Field Maintenance</u></b>		
Refitting spring rocker into secure foundations, replacement of any missing bolts/ bolt caps or other fixings	£ 200.00	
Adding inserts to large multi-climber (30x12mm) and another insert in toddler play frame	£ 55.00	
Renovating silted up surfaces and re-pinning rubber mats underneath		
2x swings, slide bottom and ladder, toddler play frame and spring rocker	£ 250.00	£ 80.00 Toddler Frame
		£ 40.00 Springy (including refit)
Renovate and resecure rubber surfacing tiles around the round about	£ 100.00	£ 160.00 Slide (including repaint)
		£ 240.00 Roundabout (including repaint)
		£ 400.00 2 x Swings (including re-paint)
		Adding 2 x slabbed areas behind yellow gates making sure there are no trip points
Dig out and add level gravel dust area (with timber border) behind both play gates. (removal of waste included)	£ 410.00	£ 109.00
Drop bolt sleeve for maintenance gate £ change the whole bolt	£ 44.00	£ 360.00 Fence repaint & drop bolt
Sand and repaint fence between the playing field and play area	£ 235.00	
Sand and re-paint the see-saw, slide and round about	£ 325.00	£ 80.00 Seesaw
		£ 120.00 A-Frame & Wheel
		£ 42.00 Topsoil estimate under mats
		£ 250.00 Paint estimate
Clean up multi-climber to remove moss and algae build up	£ 120.00	
If skip required / If van load of waste		
<b>Total cost including skip / excluding rubber matting &amp; with assumed sizing for slabs</b>	<b>£ 1,739.00</b>	<b>£ 1,881.00</b>
		<b>*excludes VAT &amp; assumes straightforward job, does not account for unforeseen items</b>